




# MIT NUCLEAR REACTOR LABORATORY

*an MIT Interdepartmental Center*



## Re-starting from scratch: Waking up MITR II Nuclear Instrumentation

Dane Kouttron

*Research Engineer*




# MIT Research Reactor (MITR-II)


- MITR-I constructed 1956-1958
- Core and process systems redesigned for MITR-II
  - Light water cooled and moderated, heavy water reflected
  - First criticality on August 14<sup>th</sup>, 1975
- Primary/Secondary systems rebuilt in 2010 for relicensing and power uprate up to 6.0 MW
- Operates 24/7 except during scheduled outages

# Profile of MITR-II

Overhead View



Cross Section



**Reactor Safety Detectors**  
Two Vertical Fission Chambers  
Two Horizontal Fission Chambers



# Swimming Detectors




## ➤ Dec 14 2022- Vertical Port view

- Vertical port plug removed, flooding of vertical ports confirmed
- There's not supposed to be primary coolant there
- Disassembly and leak discovery process begins

# Swimming Detectors



## *Pre-Disassembly Reactor Top*



# Documenting Disassembly


---



## ➤ Primary Coolant leak



# Detectors are not submersible



- As it turns out while our fission chambers are hermetically sealed, they are not intended to be submersible
- Vertical instrumentation port filling with water results in bonus neutron moderation, reduction in apparent flux.
- Fission chamber MI Cable damaged from extended moisture
  - One vertical Nuclear Safety system detector failed due to corrosion

# Detectors are not submersible



- Fission chamber directly exposed to water showed signs of cable failure
- Linear Flux chamber with top mounted connectors comically corroded






# Disassembly Begins



## *Instrumentation Vertical Ports*



# Disassembly Begins



*Cabling & detectors removed*



# Disassembly



## ➤ Early 2023

- Core De-Fueled
- Vertical Detectors, experiments, leak detection tapes removed
- Meters of cables removed
- Existing systems disturbed with ‘accelerated disassembly’
- 3D View of core tank with hardware removed [See 2023 TRT talk for more]




# Re-Assembly



## ➤ Late 2023

- Mechanical disassembly, leak identification and repair took months
- Meters of cables removed to aide in leak identification
- Existing systems disturbed with ‘accelerated disassembly’
- Re-cabling & Re-Terminating required for all of nuclear safety system

## ➤ New cables, new detector positions, what could possibly hinder restart?



# Re-Assembly



- Late 2023
  - Fuel daughter-product Neutrons nearly exhausted
  - Nuclear instrumentation issues begin!
  - Initial detector locations intended for neutron flux proportional to 6MW, required significant re-location
  - One detector failure due to MI Cable damage from re-location.



# Relocating Detectors



## ➤ Detector re-cabling

- To re position detectors closer to fuel, cable extensions fabricated
- Horizontal detector port tubes sleeved with PVC to limit resistance when re positioning detectors




## ➤ Port Plugs removed

- Existing port plugs purposely restrict detector location



## ➤ Relocating Detectors

- Full Power Fission chamber Detectors re-located to closest to core position
- Temporary high sensitivity Helium-3 detectors installed to provide better indication of core status for re-fueling
- Apparent disconnect between reactor safety system count-changes and Helium-3 counts during reflector level changes & shutdown blade height changes




# Where are my neutrons

---






# MIT NRL Digital Safety System Overview



# Mirion Preamplifier Overview



HV Supply


Detector

Logic Power & Test Functions

Pulse Mode Output

Current Mode Output


# Mirion Preamp Issues



Wide Range Preamp TKV 23

## Contents

Features and Applications  
Description  
Functional diagram  
Plug pin allocation  
Technical data  
Main dimensions  
Ordering information




## Features

- Preamp for fission chambers
- Pulse output for start-up range
- Alternate current output for intermediate range
- Signal for high voltage monitoring
- 50Ω or 75Ω line driver for long cable lengths
- Stable HF-proofed brass housing

- Facility disassembly prioritized leak location identification
- Order of operations resulted in hardware issues
  - Significant damage to channel pre-amplifiers caused by disconnecting at detector in powered down state
  - In powered-down state, cable disconnection order appears to overstress internal component
  - 4+ Month lead time on replacement units


# Mirion Preamplifier Issues



## ➤ Black box reverse engineering

- Pre-amplifier uses no component reference designators
- A number of components are no longer manufactured
- Schematic & signal level repair unavailable
- Design is 2 layer allowing for easier reverse engineering
- Through hole components appear hand assembled

# Mirion Preamplifier Issues



## ➤ Labeling and Beginning Diagnostics

- Pre-amplifier uses no component reference designators [R1, Q1, etc]
- A number of components are no longer manufactured
- Schematic & signal level repair unavailable


## ➤ Vendor repair timeline significant

- Three pre-amps initially damaged during RX disassembly

# Mirion Preamplifier Issues





Pulse Generator / Shaper  
Notes





➤ Using one working unit to Identify component failures

- Pre-amplifier uses no component reference designators [R1, Q1, etc]
- A number of components are no longer manufactured :/
- Schematic & signal level repair unavailable



# Mirion Preamplifier Issues






## ➤ Hardware issues tied to output stage issue

- Multiple units appeared to have similar failure mode, count-rate level pulse train generation
- Identical component fortunately replicable and available for purchase
- Failed push-pull output resulted in malformed pulse-mode signal



# Mirion Preamplifier Issues



➤ Component replaced with identical qualified part with appropriate QA

- They still make metal-can individual transistors?
- Surprisingly yes




# Restarting with a handful of neutrons



## ➤ 1/M Shuffle

- Full Power detectors as close to the core as possible
- Low initial counts were repeatable and counts followed reactivity removal actions (reflector level, subcritical blade motion)
- Long integration length counts now repeatable
- Initial 1/M startup achieved 70 watts at full power indication
- Reactor shutdown for subsequent restarts



# Restarting with a handful of neutrons



## ➤ 1/M Shuffle


- Full Power detectors as close to the core as possible
- Low initial counts were repeatable and counts followed reactivity removal actions (reflector level, subcritical blade motion)
- Long integration length counts now repeatable
- Initial 1/M startup achieved 700 watts at full power indication
- Reactor shutdown for subsequent restarts

## ➤ Detector Position Relocation cumbersome process


# Restarting with a handful of neutrons




DWK2 Flux % vs. CH2 W



CH6 (nA) vs. CH2 W



Flux Vs Time



## ➤ Eight 1/M Detector Shuffles

- Performing stepwise reactor 1/M restarts, verifying data, adjusting position and restarting required
- Stepwise detector relocations required not only position changes, but detector disconnection, re-cabling through port plugs, and subsequent restarting
- Initial detector positioning significantly below threshold for thermal power indication

## ➤ Getting up to megawatts had it's own hurdles

- Significant building argon levels delayed intermediary restart steps as air gaps were identified and sealed
- Data logging was somewhat manual for 1/M datasets

# Recommendations

---



## ➤ Research Reactor staffing

- Significant unplanned extended outages require extra hands
- Staffing levels generally intended to cover normal operation, not reconstruction, which results in a time consuming bottleneck
- Adopt personnel from other academic laboratories to load-share
- Communicate and plan operations scheduling

## ➤ Hardware Vendors

- Provide actual diagnostic manuals with signal acceptance criteria


# Acknowledgements



## NRL Operations and Maintenance Staff



Paul Menadier  
David Carpenter  
Adam Grein  
Taylor Tracy



# Questions?

